


## Boring Bar Sleeves



| PART No. | d   | D1 | L1  | L   | Fig. | Kgs  | Group |
|----------|-----|----|-----|-----|------|------|-------|
| BBS 25   | 8   | 35 | 65  | 70  | 1    | 0.20 | A     |
|          | 10  | 35 | 65  | 70  | 1    | 0.20 | A     |
|          | 12  | 35 | 65  | 70  | 1    | 0.20 | A     |
|          | 16  | 35 | 65  | 70  | 2    | 0.10 | A     |
|          | 20  | 35 | 65  | 70  | 2    | 0.10 | A     |
|          | MT1 | 35 | 65  | 76  | 3    | 0.20 | A     |
| BBS 32   | MT2 | 35 | 65  | 89  | 3    | 0.20 | A     |
|          | 8   | 42 | 82  | 87  | 1    | 0.40 | A     |
|          | 10  | 42 | 82  | 87  | 1    | 0.50 | A     |
|          | 12  | 42 | 82  | 87  | 1    | 0.50 | A     |
|          | 16  | 42 | 82  | 87  | 2    | 0.40 | A     |
|          | 20  | 42 | 82  | 87  | 2    | 0.30 | A     |
|          | 25  | 42 | 82  | 87  | 2    | 0.20 | A     |
| BBS 40   | MT1 | 42 | 82  | 87  | 3    | 0.50 | A     |
|          | MT2 | 42 | 82  | 89  | 3    | 0.40 | A     |
|          | MT3 | 42 | 82  | 110 | 3    | 0.40 | A     |
|          | 8   | 50 | 85  | 90  | 1    | 0.80 | A     |
|          | 10  | 50 | 85  | 90  | 1    | 0.80 | A     |
|          | 12  | 50 | 85  | 90  | 1    | 0.80 | A     |
|          | 16  | 50 | 85  | 90  | 2    | 0.60 | A     |
|          | 20  | 50 | 85  | 90  | 2    | 0.60 | A     |
|          | 25  | 50 | 85  | 90  | 2    | 0.40 | A     |
|          | 32  | 50 | 85  | 90  | 2    | 0.30 | A     |
| BBS 50   | MT1 | 50 | 85  | 90  | 3    | 0.80 | A     |
|          | MT2 | 50 | 85  | 90  | 3    | 0.70 | A     |
|          | MT3 | 50 | 85  | 110 | 3    | 0.80 | A     |
|          | 8   | 60 | 90  | 95  | 1    | 1.40 | A     |
|          | 10  | 60 | 90  | 95  | 1    | 1.40 | A     |
|          | 12  | 60 | 90  | 95  | 1    | 1.30 | A     |
|          | 16  | 60 | 90  | 95  | 2    | 1.20 | A     |
|          | 20  | 60 | 90  | 95  | 2    | 1.10 | A     |
|          | 25  | 60 | 90  | 95  | 2    | 1.00 | A     |
|          | 32  | 60 | 90  | 95  | 2    | 0.80 | A     |
|          | 40  | 60 | 90  | 95  | 2    | 0.50 | A     |
|          | MT1 | 60 | 90  | 95  | 3    | 1.30 | A     |
|          | MT2 | 60 | 90  | 95  | 3    | 1.30 | A     |
| MT3      | 60  | 90 | 110 | 3   | 1.40 | A    |       |